



WINTER HOUSE

DOE
NOV 29 1979

Vicinity of Goodrich, Sheridan County, N.D.

Photo: Window bay construction, south lateral wall, July, 1977. 11 SEP 1979

Photo credit: Kurt Schweigert
Negatives on file at: Department of Anthropology/Archaeology, University of North Dakota, Grand Forks, N.D.

#10/17



WINTER HOUSE

11 SEP 1979

Vicinity of Goodrich, Sheridan County,
North Dakota

DOE
NOV 29 1979

Photo: Wall plate and eave construction
detail, south lateral wall, May, 1979.

Photo credit: Kurt Schweigert

Negatives on file at: State Historical Soc-
iety of North Dakota, Bismarck, N.D.

#20/7



WINTER HOUSE

Vicinity of Goodrich, Sheridan County,

North Dakota NOV 29 1979 11 SEP 1979

DOE

Photo: Structure from southeast, July, 1977.

Photo Credit: Kurt Schweigert

Negatives on file: Department of Anthropology/Archaeology, University of North Dakota, Grand Forks, N.D.

3817



DOE
NOV 29 1979

WINTER HOUSE

Vicinity of Goodrich, Sheridan County, N.D.

Photo: Door frame and wall construction,
south lateral wall, July, 1977.

11 SEP 1979

Photo credit: Kurt Schweigert

Negatives on file at: Department of Anthro-
pology/Archaeology, University of North
Dakota, Grand Forks.

6/7



Winter House

Vicinity of Goodrich, Sheridan County, N.D.

Photo: Interior partition wall construction,
July, 1977

NOV 29 1979
DDE

11 SEP 1979

Photo credit: Kurt Schweigert

Negatives on file at: Dept. Anthropology/
Archaeology, University of North Dakota

#58/17



WINTER HOUSE

Vicinity of Goodrich, Sheridan County,
North Dakota

11 SEP 1979

Photo: Structure from southwest, May, 1979.

Photo credit: Kurt Schweigert

Negatives on file at: State Historical
Society of North Dakota

NOV 29 1979

6077



WINTER HOUSE

Vicinity of Goodrich, Sheridan County,
North Dakota

Photo: Ceiling treatment and decorative
design, west room, May, 1979.

Photo credit: Kurt Schweigert
Negatives on file at: State Historical
Society of North Dakota

NOV 29 1979
DOE

11 SEP 1979

#70/7